

3 July 1963



STATINTL

Reference the adjustment work done [redacted] on
July 2 - 3, it is the consensus [redacted] that the equipment was placed in as good a condition as possible at the time. Voltage drops and possible minor mechanical mal-adjustments existing at the time did not make it possible to give a final overall clearance of the quality of the operation of the [redacted] components.

STATINTL

STATINTL

STAT

Therefore [redacted] has been released as having performed all work that could reasonably requested of him at the time. This however is not to be construed as a final acceptance of the equipment. This final acceptance cannot be made until the mechanical and line voltage factors have been eliminated. This will be accomplished as soon as possible after which further checks will be made on the performance of your components.

STATINTL

STAT



STATINTL

cc: [redacted]

Orig - Addressee

1

1

[redacted] 1. - DC/TID

1 - TID/TAB

STATINTL

NPIC/TID/TAB [redacted] (3 July 1963)

STATINTL

Declass Review by NIMA/DOD

NPIC ROUTING SLIP

Approved For Release 2003/05/15 : CIA-RDP78B04747A000900050034-1

FROM: *TID/TAB*

DATE:

TO	INITIALS	DATE	FOR YOUR							
			SIGNATURE	INFORMATION	COMMENTS	CONCURRENCE	APPROVAL	ACTION	SEE REMARKS BELOW	FILE
DIR										
DEP/DIR										
EXEC/DIR										
ASST FOR OPS										
ASST FOR ADMIN										
ASST FOR P&D	XV		X		X					
CH/PSD										
CH/PD										
CH/TID										
SIO/CIA (PID)										
SIO/ARMY										
SIO/NAVY										
SIO/AF										
LO/DIA										
LO/NSA										
REMARKS:	<i>[Large rectangular redacted area]</i>									

STAT

STATINTL

Approved For Release 2003/05/15 : CIA-RDP78B04747A000900050034-1